

Download 2003 C320 Mercedes Benz Repair Manual

This guide will show you how to replace the Mass Air Flow (MAF) sensor on Mercedes Benz. If you get any of these codes P0100, P0101, P0102, P0103 and P0104 you most likely need your MAF replaced. The radiators on the Mercedes-Benz W203, like any other car, can wear out with time and age. The unit itself is expensive to replace, so before you buy a new one, pressure test the cooling system first and verify the location of any leaks. Replacing the fuel pump on a Mercedes C320 can be done without removing the fuel tank. There is an access panel under the rear seat cushion that allows servicing. Mercedes Benz Workshop and Service Manuals

The Mercedes-Benz C-Class is a compact executive automobile yielded by Mercedes-Benz. Although initially available because sedan plus station wagon body designs, the W203 series inside 2000 debuted a fastback/hatchback coupe variation which later whenever facelifted diverged into the Mercedes-Benz CLC-Class. In October