

Download Kubota L5450 Tractor Workshop Service Repair Manual

Flywheel Resurfacing If you are undertaking splitting of your Kubota tractor to service the clutch it is recommended that you resurface the flywheel – paying particular attention to the appropriate minimum thickness requirement. Kubota further states that the maximum amount of material that can be removed from any flywheel clutch surface is .060” (1.5mm).